HT SERIES





NOTICE

- This product is not intended for life or safety applications.
- Do not install this product in hazardous or classified locations.
- Read and understand the instructions before installing this product.
- Turn off all power supplying equipment before working on it.
- The installer is responsible for conformance to all applicable codes.

PRODUCT IDENTIFICATION

				Temp Cal	
Accuracy	NIST	Setpoint		Certificate	Option
нт 🖵	\Box	A	S	\Box	
1 = 1%	N = NIST	= Analog	= CE	0 = None	B = 100R Platinum, RTD
2 = 2%	(1 & 2% only)			1 = 1 point Cal	C = 1k Platinum, RTD
3 = 3%	X = No			Validation	D = 10k T2, Thermistor
5 = 5%	(2, 3, 5% only)			2 = 2 point Cal	E = 2.2k, Thermistor
				Validation	F = 3k, Thermistor
					G = 10k CPC Thermistor
					H = 10k T3, Thermistor
					J = 10k Dale, Thermistor
					K = 10k w/11k with Shunt,
					Thermistor
					M = 20k NTC, Thermistor
					N = 1800 ohm TAC, Thermistor

HT SERIES

LCD Wall Mount with Analog Setpoints 1% NIST, 2% NIST, 2%, 3%, 5%

Installer's Specifications

Input Power*	15 to 30VDC/24VAC, 100mA max.
Outputs	Switch-selectable 4-20mA or 0-10V/0-5VDC
-	(switch affects both outputs)
RH Sensor	Digitally profiled thin-film capacitive (32-bit mathematics)
	U.S. Patent 5,844,138
Accuracy at 25°C from 10-80% RH	** ±2%, 3%, or 5% models
	\pm 1% at 20-50% RH (Multi-point calibration NIST traceable)
Reset Rate***	24 hours
Stability	\pm 1% @ 20°C (68°F) annually, for two years
Linearity	Included in Accuracy spec.
Operating Humidity Range	0-100% RH (non-condensing)
Temperature Coefficient	\pm 0.1%RH/°C above or below 25°C (typical)
Operating Temperature Range	10°-35°C (50°-95°F)
Temperature Accuracy	$\pm 1.0^{\circ} \text{C} (\pm 1.8^{\circ} \text{F})$
Scaling	RH: 0-100% RH; Temp: 10°-35°C (50°-95°F) or
	0°-50°C (32°-122°F) menu selectable
Calibration Offset	RH: Adjustable $\pm 9.9\%$ in 0.1% increments;
	Temp: Adjustable ±5.0°C (±9.9°F) in 0.1° increments
Setpoint Range	RH: 10-80% RH in 1% increments;
	Temp: Minimum to Full Scale in 1° increments

^{*} One side of transformer secondary is connected to signal common, so an isolation transformer or dedicated power supply may be required.


QUICK INSTALL

- 1. Select a mounting location away from ventilation sources. The sensor should be mounted on a vertical wall, about 4 ½ feet above the floor.
- 2. Affix the backplate to the wall.
- 3. Wire the device. Refer to wiring diagram.
- 4. Install Cover.

Q = 1uA/C, Linitemp R = 10k US, Thermistor S = 10k 3A 221

T = 100k, Thermistor U = 20k "D", Thermistor

DIMENSIONS



^{**} Specified accuracy with 24VDC supplied power with rising humidity

^{***}Reset Rate is time required to recover to 50% RH after exposure to 90% RH for 24 hours RTD/Thermistors in wall packages are not compensated for internal heating of product.

INSTALLATION

1. Remove the cover by pressing the tab at the top of the sensor while pulling outward from the top of the cover.



2. Remove the backplate by unfastening the sensor from the bottom of the backplate and pivoting the sensor outward.




3. Punch out openings in the backplate.




4. Position the sensor vertically on the wall, 4 ½ feet above the floor.



5. Mount the backplate onto the wall using the screws provided.





7. Install and configure the sensor.



RH YES/NO JUMPER:

YES - allows user to change RH setpoint NO - user can NOT change RH setpoint

TEMP YES/NO JUMPER:

YES - allows user to change TEMP setpoint

NO - user can NOT change TEMP setpoint

RUN/CAL JUMPER:

CAL Mode - allows full access to all features.

RUN Mode - allows access to relay setpoints ONLY.

8. Install the cover and snap into place.




TEMP SENSOR

RH SENSOR

HT CALIBRATION INSTRUCTIONS

- 1. Temperature calibration allows for calibration offset of $\pm 10^{\circ}$ F, user discretion. RH and TEMP can be field calibrated by moving RUN/CAL jumper to CAL position.
- 2. Relative humidity allows for calibration offset of $\pm 10\%$ RH, user discretion.

HT OPERATION INSTRUCTIONS



Normal Operation

NORMAL MODE

4	5	5	%	R	Н
6	8	5		0	F

Temperature Selection

Use the (+) and (-) buttons to scroll to the Thermostat mode:

S	Ε	T	P	0	I	N	T
		7	0				F

press \pm to change, press * to select; setpoint in °C if Celsius units are selected

Humidity Selection

Use the (+) and (-) buttons to scroll to the Humidistat mode:

S	Ε	T	Р	0	I	N	T
		4	5		%	R	Н

press ± to change, press * to select


MENU




4	5	•	5	%	R	Н
6	8		5		0	F

CONFIG/CAL MODE

(Enter by any keypress when Run/Cal jumper is in CAL position)



press ± to change, press * to select



press ± to change, press * to select; setpoint in °C if Celsius units are selected

				7			
S	E	T	Р	0	I	N	T
		4	5		%	R	Н


press ± to change, press * to select

			•	,		
C	Α	L		T		
+	0		0			F

press \pm to change, press * to select; setpoint in $^\circ$ C if Celsius units are selected

			•	7		
C	Α	L		R	Н	
+	0		0			%

press ± to change, press * to select



Output scaling (does not affect LCD display)

> press \pm to change, press * to select; options are 50-95°F (10-35°C) or 32-122°F (0-50°C)

Only for switch in Volts position

			•	,			
	0	U	T	Р	U	T	
	0	-	1	0	٧		

press ± to change, press * to select