

# HT SERIES



# HT SERIES

## LCD Wall Mount with Relay Setpoints

### 1% NIST, 2% NIST, 2%, 3%, 5%

#### Installer's Specifications

Power Supply*	15 to 30VDC/24VAC, 100mA max.
Outputs	2 Form C (SPDT), 1A 30VDC, resistive, 30W max.
RH Sensor	Digitally profiled thin-film capacitive (32-bit mathematics) U.S. Patent 5,844,138
Accuracy at 25°C from 10-80% RH***	±2%, 3%, or 5% models ±1% at 12-40% RH in mA output mode; ±1% at 30% RH in voltage output mode (Multi-point calibration NIST traceable)
Reset Rate**	24 hours
Stability	±1% @ 20°C (68°F) annually, for two years
Hysteresis***	RH: 1.5% (typical), Temp: 1° to 5°C in 1°C increments (1° to 10°F in 1°F increments)
Linearity	Included in Accuracy spec.
Operating Humidity Range	0-100% RH (noncondensing)
Temperature Coefficient	±0.1%RH/°C above or below 25°C (typical)
Operating Temperature Range	10°-35°C (50°-95°F)
Temperature Accuracy	± 1.0°C (± 1.8°F)
Scaling	RH: 0-100% RH; Temp: 10°-35°C (50°-95°F) or 0°-50°C (32°-122°F) menu selectable
Calibration Offset***	RH: Adjustable ±9.9% in 0.1% increments; Temp: Adjustable ±5.0°C (9.9°F) in 0.1° increments
Setpoint Range***	RH: 10-80% RH in 1% increments; Temp: Minimum to Full Scale in 1° increments

## NOTICE

- This product is not intended for life or safety applications.
- Do not install this product in hazardous or classified locations.
- Read and understand the instructions before installing this product.
- Turn off all power supplying equipment before working on it.
- The installer is responsible for conformance to all applicable codes.

### PRODUCT IDENTIFICATION

HT	Accuracy	NIST	Setpoint	Temp Cal Certificate	Option
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	1 = 1%	N = NIST	= Relay	0 = None	B = 100R Platinum, RTD
	2 = 2%	(1 & 2% only)		1 = 1 point Cal Validation	C = 1k Platinum, RTD
	3 = 3%	X = No		2 = 2 point Cal Validation	D = 10k T2, Thermistor
	5 = 5%	(2, 3, 5% only)			E = 2.2k, Thermistor
					F = 3k, Thermistor
					G = 10k CPC Thermistor
					H = 10k T3, Thermistor
					J = 10k Dale, Thermistor
					K = 10k w/11k with Shunt, Thermistor
					M = 20k NTC, Thermistor
					N = 1800 ohm TAC, Thermistor
					Q = 1uA/C, Linitemp
					R = 10k US, Thermistor
					S = 10k 3A 221
					T = 100k, Thermistor
					U = 20k "D", Thermistor

\* One side of transformer secondary is connected to signal common, so an isolation transformer or dedicated power supply may be required.

\*\* Reset Rate is time required to recover to 50% RH after exposure to 90% RH for 24 hours.

\*\*\* Specified accuracy with 24VDC supplied power with rising humidity.


To maintain CE compliance the connected power supply must have a CE mark supporting LV + CE directives.

RTD/Thermistors in wall packages are not compensated for internal heating of product.

### QUICK INSTALL

1. Select a mounting location away from ventilation sources. The sensor should be mounted on a vertical wall, about 4 ½ feet above the floor.
2. Affix the backplate to the wall.
3. Wire the device. Refer to wiring diagram.
4. Install Cover.

### DIMENSIONS



**INSTALLATION**


1. Remove the cover by pressing the tab at the top of the sensor while pulling outward from the top of the cover.



2. Remove the backplate by unfastening the sensor from the bottom of the backplate and pivoting the sensor outward.



3. Punch out openings in the backplate.



4. Position the sensor vertically on the wall, 4 ½ feet above the floor.




correct




incorrect

5. Mount the backplate onto the wall using the screws provided.




Five screwholes available; use a minimum of two for secure mounting.


6. Wire the backplate.



7. Install and configure the sensor.



**WARNING:** Output select must be correct before applying power.





8. Install the cover and snap into place.




**HT CALIBRATION INSTRUCTIONS**

1. Temperature calibration allows for calibration offset of  $\pm 9.9^{\circ}\text{F}$ , user discretion. RH and TEMP can be field calibrated by moving RUN/CAL jumper to CAL position.
2. Relative humidity allows for calibration offset of  $\pm 10\%$  RH, user discretion.



**HT OPERATION INSTRUCTIONS**



**Normal Operation**

**NORMAL MODE**

4	5	.	5	%	R	H
6	8	.	5		°	F

**Temperature Selection**

Use the (+) and (-) buttons to scroll to the Thermostat mode:

S	E	T	P	O	I	N	T
		7	0				F

press  $\pm$  to change, press \* to select; setpoint in  $^{\circ}\text{C}$  if Celsius units are selected

**Humidity Selection**

Use the (+) and (-) buttons to scroll to the Humidistat mode:

S	E	T	P	O	I	N	T
		4	5	%	R	H	

press  $\pm$  to change, press \* to select

**MENU**

**NORMAL MODE**

4	5	.	5		%	R	H
6	8	.	5			°	F

↓

**CONFIG/CAL MODE**  
(Enter by any keypress when Run/Cal jumper is in CAL position)

U	N	I	T	S			
*	°	F				°	C

press ± to change, press \* to select

	R	E	L	A	Y	S	
*	R	H					T

press ± to change, press \* to select

S	E	T	P	O	I	N	T
		4	5		%	R	H

press ± to change, press \* to select

- OR -

S	E	T	P	O	I	N	T
		7	0				F

press ± to change, press \* to select;  
setpoint in °C if Celsius units are selected

D	E	A	D	B	A	N	D
			5		%	R	H

press ± to change, press \* to select

D	E	A	D	B	A	N	D
			4				F

press ± to change, press \* to select;  
deadband in °C if Celsius units are selected

C	A	L		T			
+	0	.	0				F

press ± to change, press \* to select;  
setpoint in °C if Celsius units are selected

C	A	L		R	H		
+	0	.	0				%

press ± to change, press \* to select

T	E	M	P		S	E	T
+	5	0			+	9	5

Output scaling  
(does not affect LCD display)

press ± to change, press \* to select;  
options are 50-95°F (10-35°C) or 32-122°F (0-50°C)

	O	U	T	P	U	T	
	0	-	1	0	V		

Only for switch in  
Volts position

press ± to change, press \* to select